

PAPERS LAID ON THE TABLE.**Postponed Questions and Answers.**

Sri Kadidal MANJAPPA (Minister for Revenue and Public Works).—I beg to lay on the Table of the House replies to 47 questions remaining for answer from the last Session and replies to 6 questions which were promised in the last Session. The Questions and Answers will be printed in to-day's proceedings.

—————

**Major and Minor Tanks in
Nagamangala Taluk.**

**Q.—1. Sri M. SANKAR LINGE
GOWDA (Nagamangala).—**

Will the Government be pleased to state :—

the names of major and minor tanks situated in the villages of Nagamangala

taluk with the area under *atchkat* and the assessment of each tank with the remarks - 'restored or un-restored'; and also the condition of each tank, and the amount spent from the year 1881 to the end of the year 1951-52?

A.—Sri KADIDAL MANJAPPA
(Minister for Revenue and Public Works).—

Statement given below. Regarding the amount spent from the year 1881 to end of 1951-52, the figures are only approximate as could be obtained from the available records. Tanks with an *atchkat* of less than 5 acres are not taken into account.

The column "condition of tank" could not be filled in the case of a few tanks, as information in respect of them is not readily available.

Sl. No.	Name of village	Name of tank	Atch- kat	Assessment	Restored or unrestored	Condition of tank	Amount spent from 1841 to end of 1951-52	Remarks
1	Bagamangala	Meior Tanks- Naganakere Tank	400	Rs. 400	Restored in 1936-7	Good	Rs. 31,500
2	Kelagere	78 Wet	370	do 1895	Under restoration	14,799
3	Melhalli	Tank	22 Gai- d-n.	1934-35	Fair, in need of main- tenance works.	16,572
4	Nagamangala	Ammanakatte	81	386-40	Restored in 1938-97	Fair	3,418
5	Do	Sulekere	380	2010	do 1937-92	Good but maintenance neglected.	5,000
6	Do	Singarasinakere	106	423	do 1918-22	Fair; maintenance to bund necessary.	32,000
7	Do	Hirekere	328	1652	do 1936-37	Good	54,000
8	Anchechittanahalli	Tank	120	do 1936-87	Good	59,400
9	(Makatte) Madalahalli	Tank	135	do 1891-96	Good but bed silted up.	32,437
10	Bindenahalli	Tank	386	1522	do 1883	Fair	82,165
11	Devalapura	Urumundinakere	110	492	do 1893	Fair; requires mainie- nance and some im- provement works.	7,730
12	Dondemadaballi	Kodiagikere (Hosa- k re).	80 Ac.	Being restored from 1942-43	Good	26,182
13	Hiduva	Tank	575	2299	do 1936-37	Good	1,25,000
14	Kotebetta	Palkere	473	Water rate. 2555	do 1902	Good, bund mainte- nance neglected by Talukda's.	1,00,000
15	(Garukahalli) or Ragu- rapura.	Tank	174	1025	do 1899-1902	Good, bund in need of maintenance, and R. Chal, to be improved.	16,983
16	Somanahalli	Tank	99	323	do 1889	Good, channel tampered by Talukda's.	12,000
17	Rhusandra	Tank	114	460	do 1898	Bed badly silted up	30,091
18	Chikayagali	Huchikere	401	do 1935-56	Good, Rt. Bank Chl. to be improved.	1,18,000
19	Manchipatna	Tank	229	do 1927-28	Fair, capacity being in- creased.	65,000
20	Doddajataka	Dasanaker	125	508	do 1884-98	Fair, requires improve- ments.	17,000
21	Bellur	Tank	615	3315	do 1899	Fair, in need of general repairs.	37,500

Sl. No.	Name of village.	Name of tank	Atchakat	Assessment	Restored or unrestored	Condition of tanks	Amount spent from 1891 to end of 1951-52	Remarks
22	Honnenahalli	Major Tanks— Tank	192	Rs. 742	Being restored from 1889.	Fair, small improvements.	Rs. 52,980
23	Thigalanahalli	Tank	113	502	do 1891	Do repairs	46,200
24	Arani	Tank	76	392	do 1932-36	Good	7,500
25	Mudigere	Tank	70	...	do 1938-39	Good	31,000
26	Koppa	Tank	138	722	do 1898	Good	13,730
27	Belagumba Kelakere	Tank	103	493	do 1896	Fair, in need of certain repairs.	12,500
28	Ramachandra Agrahar.	Tank	101	440	do 1894	Fair, bed silted up	25,200
29	Honnayara	Hirekere	265	1049	do 1902	Fair	31,500
30	Do	Kalkere	79-13	842/8	Fair, Maintenance work badly neglected.	5,522	Since 1939.
31	Bindiganavale	Kadagikere	556	2205	do 1896	Good	23,000
32	Dadaga	Tank	4-3	2228	do 1889	Bad	56,500
33	Hiraganahalli	Tank	556	2393	do 1883	Good, requires minor repairs.	40,000
34	Bommanahalli	Tank	123-19	402	do 1935-36	Good	28,026
35	Jodi Alpanahalli	Huchikere	(195)	...	Under restoration	9,000
36	Biarekere	Hirekere	(144)	...	Newly sanctioned for restoration.
1	Kargere	Tank	45	Rs. 225	Restored in 1946	Good, Sluice requires new plug and rod.	Rs. 12,274	...
2	Byadarahalli	Hosakere	22	...	Being restored from 1949	...	8,591	Restoration work under progress.
3	Deeravarapura	Tank	20	...	Do 1944	Good Irrigation Chl. requires repairs.	16,580	Do
4	P. duvalaneralekere (Kurubarahalli).	Tank	20	...	Do 1945	Good	10,644	Do
5	Yegat Halli	Shanbhoganakatte	20-5	...	Do 1945-46	Fair	2,161	Feeder channel has been proposed.
6	Tuppadamadu	Surankere	17	...	Do 1944-45	Fair, maintenance to bund neglected.	4,500	...
7	Jodi Hulekere	Tank	14	48	Not restored
8	Malreppur	Hosakere	10	22	Restored 1944-45	Fair natural weir washed off & requires to be replaced by masonry weir.	1,527	...

MINOR TANKS
(With atchkat of 5 acres and more).

	Hullnahalli	Urumundinakere	47	226	Do	1906	Fair	15,123	Estimate for increasing capacity is under operation.
10	Maddanahatti	Tank	57	173	Do	1907	Fair	9,500	...
11	Mai arapota	Do	55	116	Do	1927-28	Bad	913	...
12	Thammalakanahalli	Do	57	...	Do	1934-35	Good, weir requires prospective works.	5,100	...
13	Samparabai	Do	30	...	Do	...	Fair	7,987	...
14	Dandiganahalli	Do	25	125	Do	...	Bad	90	To be taken up for restoration.
15	Hulleshahalli	Chikere	25	...	Being restored	1916-47	Good	7,112	Estt. for increasing capacity under operation.
16	Dev ramallanakana-	Tank	24	91	Restored	...	Fair	1,950	...
17	Annahalli	Do	21	73	Not restored	...	Good, bund requires maintenance.	120	Further figures not available.
18	J kkanahalli tank	Do	16	52	Do	...	Bad	...	Not available
19	(Kemmigowdanakere)	Do	15	55	Do	...	Good, Chnl. to be improved.	1,672	Do
20	Doddaupla	Tank	13	43	Restored	1888	Fair, bund needs earthwork.	1,672	...
21	Thubinakere	Do	10	34	Do	...	Do	465	...
22	Thubinakere	Do	9	26	Not restored	...	Fair	...	Not available
23	Chikkanahalli tank	Do	7	24	Do	...	Good	60	...
24	Devaramadhallikere	Do	65	264	Restored	...	Fair, maintenance neglected.	3,050	...
25	Chinya tank	Do	41	...	Restored	1943	Fair	18,147	Two new sluices and channels proposed.
26	Manahalli Mathikere	Do	39	124	Restored	...	Bad	7,627	Not available
27	Thammadhalli	Jaranakatte	38	120	Do	...	Fair, bed badly silted up.
28	Thammadhalli	Do	43	44	Do	1946-47	Fair	6,260	...
29	Manahalli Mathikere	Do	13	65	Being restored	...	Fair, W.W. & Aqueduct needs protective works.	4,215	...
30	Thammadhalli tank	Do	20	...	Restored	1946-7	Fair, bund requires maintenance & sluice repairs.	2,740	...
31	Thammadhalli	Urumundinakere	15	56	Not restored	...	Fair	7,746	Not available
32	Gangavadi	Koppalakere	13	...	Being restored	1946-47	Fair, there is a leak in the bund to be closed.
33	Hindasaballi	Modivukatte	13	34	Not restored	...	Fair
34	Madavudara	Urumundinakere	12	41	Do
35	Sukdhare	Chikkanakatte	9	27	Do
36	Manahalli	Hulleshahalli	8	25	Do
37	Kalligudi	Ajalkattakatte	8	25	Do
38	Kalligudi	(Gumladakatte)	8	20	Do	...	Fair, irrigation Chnl. to be improved.

Sl. No.	Name of Village	Name of Tank	Atobkat	Assessment	Restored or unrestored	Condition of Tank	Amount spent from 1881 to end of 1951-52	Remarks
33	Handenahalli ka'ta	(Gomaladakatte)	6	20	Not restored	Fair	Rs.	...
40	Medahalli Thimmanakatte	Do	5	12	Do
41	Lakkenahalli tank	Do	6	...	Restored 1941-52	Good, requires earth work to bund.	26,720	...
42	N. Nigere	Hatna tank	64	...	Do 1934-35	Fair, bund weak & do	16,200	...
43	Betadakote	Tank	55	...	Do 1927-28	Fair, requires petty repairs	9,820	...
44	Chunchanahalli	Aynakatte	47	142	Do	Fair, requires aid Impts.	1,273	Estt. sanctioned works to be taken up.
45	Nagathihalli	Gowdanakere	47	207	Restored	Good, requires maintenance bund.	2,203	...
46	Karijeeraballi	Tank	80	Water rate	Restored 1930-51	Good	85,545	...
47	Nagathihalli	Pagalgere	60	...	Under restoration	Fair	18,187	...
48	Thoenavilakere	Tank	28	...	Restored 1933-47	Havily silted up otherwise fair.	8,044	...
49	Yalchikere	Dalavoykatte Tank	25	67	Not restored	Not available
50	Byalakere	Tank	19	91	Restored in 1927-58	Bad	5,572	...
51	Chenchikatte	Tank	20	72	Not restored	Good
52	Hampapura	Naganakere Tank	110	...	Under restoration 1946-57	Fair	9,269	...
53	Biravandura	Tank	20	75	Restored	Good	2,378	...
54	Byalakere	Chikkanakatte	5	...	do 1941-42	...	1,240	...
55	Siddapur Gowdanakatte	do	10	240	do 1860-61	Good	3,000	...
56	Hannavara Hulikere	do	43	16	do 1878	Fair, maintenance neglected.	2,684	...
57	Choleaballi Tank	do	40	...	do 1941-45	Fair maintenance neglected.	18,500	...
58	Sathenaballi	Nakkanakere	52	Water rate 260	do 1941-43	Fair, leaks in bund to be closed.	21,410	...
59	Kadababalli	Urumandinakere	38	158	do 1938	Fair, bund to be strengthened.	4,000	...
60	Jakkundi	Tank	25	...	do 1947-23	...	2,744	...
61	Kadababalli	Chennegowdanakatte...	13	73	do 1936	Good, feeder encrusted by rains.	8,740	...
62	Voddarahalli	Hunakatte	16	64	do 1947-47	...	11,800	...
63	Bettadahalli	Malledevarakatte	14	35	do 1941	...	4,621	...

	Tank	8	27	Not restored	Bad	Nil	Not available
64	Jodi dadabala	...	36	do
65	Jamhalli	10	52	Under restoration	...	5,380	do
66	Hannanahalli	14	...	do	do
67	Korvaungundi	9	...	do
	Hun-sakatte,						
68	Jacharayakannahalli	7	19	Not restored	Fair	...	do
69	Gunjayahalli	6	...	do	Good	28,200	do
70	Padanudi	40	...	Restored 1942-43	Good	8,938	...
71	Vaddarahalli	24	...	do 1943-44	Bad	25,000	...
72	Tholali	80	...	do	...	1,000	...
73	Jodithalli	do
74	Kaueenahalli	20	...	do
		Acres Garden + 30 wet.
75	Ambalaj-eraballi	32	...	Acres 192 water
		rate.
76	Gollarahalli	19	...	Acres 11; water rate	Recently sanctioned for re-foresting.